



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration


- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Melt Temperature

Modified on Sunday, 01 February 2015 04:44 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

(10) » [Screw Cooling](#) » [Screw Wear](#) » [Melt Temperature](#)

Melt Temperature  
Vol. 17 #2, July 1990


Meaningful melt temperature readings are difficult to obtain.

A reasonable indication of melt temperature with standard sheathed T/C's can only be seen if the adaptor where the melt T/C is located is set near actual melt temperature. This may require some adjustment while watching the melt temperature reading.

See also:

- [Adjustable melt TC](#)
- [Temperature control](#)
- [Temperature controller calibration](#)
- [Temperature measurement 1](#)
- [Temperature measurement 2](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .