



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Brass Tools 2

Modified on Sunday, 01 February 2015 05:12 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

(10) » [Drive Train](#) » [Screw Removal 1](#) » **[Brass Tools 2](#)**

Brass Tools 2
Vol. 17 #4, Mar. 1991


A good idea, but most tools are Berlium Copper. These are very hard and should not be used. They are no better than steel.

Better to buy brass and make your own tools.

See also:

- [Brass tools 1](#)
- [Brass bolts on flange collar](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .