



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Decreased Motor Amps

Modified on Sunday, 01 February 2015 11:51 PM by [mplier](#) Categorized as [Extrusion Hints](#) 
(10) » [Vacuum Pump Discharge](#) » [Tools](#) » [Decreased Motor Amps](#)

Decreased motor amps
Vol. 23 #3, Dec. 1996

The first indication of a loss of feed to an extruder is often a drop in motor amps - but ammeters rarely have an alarm.


Another early indication is zone 1 barrel temperature, which will under or over shoot the set point depending on whether the process is heating or cooling. Temperature controllers do usually have alarms, however. Operators should be trained to look at motor amps and check the hopper immediately upon seeing a zone 1 temperature alarm.

- Bill Kramer

See also:

- [Barrel zone override](#)
- [Drive motor start up](#)
- [Drive speed controller](#)
- [Heater amps](#)
- [High motor amps](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .