



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Document/Document/Document

Modified on Monday, 02 February 2015 01:14 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 
(10) » [Purge - Close Vent](#) » [Drying Temperature](#) » **Document/Document/Document**

Document/Document/Document
Vol. 27 #2, November 2000


If it is not in writing, it never happened. Also, when developing checklists, always make the checks objective, not subjective. A piece of equipment is not "cool, warm, hot"- it is ___°C.

- Bill Davis, Poly-America

See also:

- [Data collection 1](#)
- [Extrusion data sheets](#)
- [Screw performance](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .