



## Navigation



### Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

### Search the Wiki

 >>

### Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

### Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

### Administration

- [Administration](#)
- [File Management](#)

### Brought to you by:

The SPE Extrusion Division Board of Directors



# Mark the Bubble

Modified on Sunday, 01 February 2015 05:02 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Screw Design](#) » [Calibrate Tachs](#) » **Mark the Bubble**

Mark the Bubble  
Vol. 17 #3, Dec. 1990

Pinching a blown film bubble to mark an adjustment can sometimes lead to a hole in the bubble. Try using crayons they work great!

See also:

- [Start up help](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)