



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Time Dimension

Modified on Sunday, 01 February 2015 05:41 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 
(10) » [Low Viscosity Addition](#) » [Temperature Controller Calibration](#) » [Time Dimension](#)

Time Dimension
Vol. 19, #2, June 1992


Remember the time dimension to mixing problems. An extruder cannot compensate for time dependent variations in composition or material quality beyond about 1/10 of the extruder's residence time.

Beyond that, you must correct the problem upstream of the extruder by improved feeder accuracy or by effective pre blending.

See also:

- [Colored mixing drums](#)
- [Extruders](#)
- [High-low melt blends](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .