



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



Temperature Control

Modified on Sunday, 01 February 2015 05:54 PM by [mpieler](#) Categorized as [Extrusion Hints](#) (10) » [Head Pressure](#) » [The Art of Details](#) » [Temperature Control](#)

Temperature Control
Vol.20 #1, Mar., 1993

Many gray hairs are caused by temperamental temperature control systems that are either out of calibration or poorly adjusted. Unless the set point and the actual reading on any barrel zone are within 3 degrees F (preferably 1 degree F), you are not controlling the process.

Find out why.

See also:

- [2 machines, 1 material](#)
- [Barrel thermocouple maintenance](#)
- [Barrel zone override](#)
- [Cooling water](#)
- [Extruders](#)
- [Seated TCs](#)
- [Temperature controller calibration](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)