



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki


»

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Die Cleaning

Modified on Sunday, 01 February 2015 11:34 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

(10) » [Power Factor](#) » [Zirconia Blades](#) » [Die Cleaning](#)

Die cleaning
Vol. 23 #2, Oct. 1996


Die and screws can be cleaned using a mixture of automatic transmission fluid and a non chlorine household cleaner, i.e., Dutch Boy. Mixing the two together forms a paste which is used to clean the metal parts.

If chlorine is present it could etch chrome plating.

See also:

- [Die and screw cleaning](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .