



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



Removing Gels

Modified on Sunday, 01 February 2015 11:36 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Die Cleaning](#) » [Twin Screw Help](#) » **Removing Gels**

Removing gels
Vol. 23 #2, Oct. 1996

For pushing crosslinked (gelled) polyolefins, use a mix of the most viscous resin run and powdered or flake stearic acid.

A 10 20% level of acid works well to soften caramelized resin and allows it to be pushed out.

See also:

- [Gel identification](#)
- [Gels 1](#)
- [Gels 2](#)
- [Purging gels](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)