



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Eye Protection

Modified on Sunday, 01 February 2015 11:37 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Training](#) » [Unmelt Gels](#) » [Eye Protection](#)



Eye protection
Vol. 23 #2, Oct. 1996


Always wear eye protection when standing near a pressurized die. Don't be fooled into thinking polymers are too viscous to "splash" out of die running at steady state.

Air pockets from a screen change or decomposition gasses from a hot spot can expand rapidly when exiting a die spraying hot polymer several feet through the air.

See also:

- [Flex tube safety](#)
- [For safety's sake 1](#)
- [Hoppers](#)
- [Hose clamp safety](#)
- [Razor knives](#)
- [Safety](#)
- [Safety 2](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .