



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Startup Timers

Modified on Sunday, 01 February 2015 11:53 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 
(10) » [New Screw Shank Lubricant](#) » [Pump Acceleration Rate](#) » **Startup Timers**

Startup timers
Vol. 24 #1, March 1997

If you are on a one or two shift operation, there is low cost equipment available that will turn on the power to the extruders hours before you arrive at the shop. You will be amazed at the increased product run time. This worked well for me.


Check with the utility company.

- Don Biklen, Springbriar

See also:

- [Start up 1](#)
- [Start up 2](#)
- [Start up efficiency](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .