



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



# Pressure Wash Extrusion Lines

Modified on Monday, 02 February 2015 12:13 AM by [mpieler](#) Categorized as [Extrusion Hints](#) (10) » [PET Dryer Instrumentation](#) » [Poor Stranding](#) » [Pressure Wash Extrusion Lines](#)



Pressure wash extrusion lines  
Vol. 24 #2, Sept. 1997

New technology now permits using dry ice (CO2) to "pressure wash" extrusion lines (especially blown film towers) with a dry cleaner having no adverse effect on adjacent electrical equipment.

The method is quite effective in removing build up low molecular weight waxes.

- Paul Bowen, Quantum Chemical Co.

See also:

- [Aligning a blown film tower](#)
- [Start up help](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)