



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



Avoid Feed Stock Fluidization

Modified on Monday, 02 February 2015 12:21 AM by [mpieler](#) Categorized as [Extrusion Hints](#) [\(10\)](#) » [Gear Pumps](#) » [Protect the Barrel](#) » **[Avoid Feed Stock Fluidization](#)**

Avoid Feed Stock fluidization
Vol. 24 #3, Dec. 1997

Have feeders which handle powder feed stock as close to the extruder as is possible to avoid fluidization of the feed stock which may result in a feeding limit or other problems.

- Paul Andersen, Werner & Pfleiderer

See also:

- [Feed rate limited](#)
- [Feed stock supply](#)
- [Interactions](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)