



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration

- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Drying Temperature

Modified on Monday, 02 February 2015 01:14 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

[\(10\)](#) » [Interactions](#) » [Purge - Close Vent](#) » [Drying Temperature](#)

Drying Temperature  
Vol. 27 #2, November 2000


When drying moisture sensitive materials, material temperature has the greatest effect on drying performance. Therefore, the drying hopper should always be insulated.

- Pete Stoughton, Conair

See also:

- [Close loop dryer](#)
- [Condensation](#)
- [Dehumidifying dryers](#)
- [Pre-drying moisture sensitive polymers](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .