



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Improve Melt Quality

Modified on Monday, 02 February 2015 01:15 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 
(10) » [Melt Pressure Indicator](#) » [Twin Screw Extruder](#) » **Improve Melt Quality**

Improve Melt Quality
Vol. 27 #2, November 2000


When blending polymers with different melting points and unmixed material is evident in the extrudate from the die, add 300-1000 ppm of a PPA to improve melt quality.

- Tom Butler, Dow Chemical Co.

See also:

- [Melt delivery](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .