



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

 »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



High Melt Temperature

Modified on Thursday, 26 February 2015 04:10 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Designing Extrusion Lines](#) » [Pumping Instability](#) » [High Melt Temperature](#)

High Melt Temperature
Vol. 33 #1, Summer 2006

The screw speed is a determining factor driving melt temperature in a single screw extruder. Barrel cooling is effective at screw speeds less than 50 rpm, but not so above that. Reducing the outlet pressure (die opening, etc.) can help reduce temperature.

– Barry Morris, DuPont

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)