



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



# Extruders

Modified on Sunday, 01 February 2015 01:31 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Start Up Help](#) » [Screen Packs 1](#) » [Extruders](#)

Vol. 16 #2, Dec. 1989 - Extruders

Extruders of different manufacture will often require different barrel temperature settings even though the screw designs are identical.

This is due to heater wattage, coolant flow rates, thermocouple locations, barrel dimensions, etc. Age of the extruder can also have an effect.

See also:

- [Barrel zone override](#)
- [Calibrate tachs](#)
- [Data collection 1](#)
- [Extruder cooling](#)
- [Extruder drive](#)
- [Extruder log book](#)
- [Feed throats](#)
- [Head pressure](#)
- [Lab extruders](#)
- [Plot extruder performance](#)
- [Screw design](#)
- [Screw specifications](#)
- [Time dimension](#)
- [Worn barrel](#)
- [2 machines 1 material](#)
- [The art of details](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)