



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Electric Screwdrivers

Modified on Sunday, 01 February 2015 01:47 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

[\(10\)](#) » [Extruders](#) » [Brass Tools 1](#) » [Electric Screwdrivers](#)


Vol 17 #1, Feb. 1990 - Electric Screwdrivers

The new, portable, electric screwdrivers are very useful. With the new Allen tips, they speed up removing bolts when disassembling dies, or for installing sheet metal guards on the extruder.

See also:

- [Screw removal 1](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .