



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

 »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



Underwater Pelletizer

Modified on Sunday, 01 February 2015 05:19 PM by [mpieler](#) Categorized as [Extrusion Hints](#) (10) » [No Service Call](#) » [Twin Screw Changes](#) » [Underwater Pelletizer](#)



Underwater Pelletizer
Vol. 18 #2, July 1991

When using an underwater pelletizer, check the knife sharpness and the screen of the spin dryer for fouling.

These two items can cause fuzzy/poor cut pellets and poor final moisture control.

See also:

- [Check it out](#)
- [Spin dryer](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)