



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Razor Knives

Modified on Sunday, 01 February 2015 05:27 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

(10) » [High Motor Amps](#) » [Gauge Systems](#) » [Razor Knives](#)

Razor Knives
Vol. 19 #1, Feb. 1992


Razor knives are used to cut scrap off rolls. Probably, the best advise is don't use them.

If necessary, one procedure to increase safety is to insist the operator hold the knife with both hands. This eliminates cutting the non knife hand or arm. It is also more difficult to cut a leg if both hands stay on the knife.

See also:

- [For safety's sake 1](#)
- [For safety's sake 2](#)
- [Safety](#)
- [Safety 2](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .