



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

 »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



The Art of Details

Modified on Sunday, 01 February 2015 05:53 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Extruder Drive](#) » [Head Pressure](#) » **[The Art of Details](#)**



The art of details
Vol.20 #1, Mar., 1993

Extrusion is the art of detail. The more you pay attention to details, the less hassle you will get from the process.

"If it ran well once, it will always run well unless something is different. Correct the problem, do not compensate".

See also:

- [Extruders](#)

[Return to Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)