



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Water Cooling

Modified on Sunday, 01 February 2015 06:12 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

(10) » [Worn Screw](#) » [Extruder Log Book](#) » [Water Cooling](#)



Water Cooling
Vol.20 #2, July 1993


Water is a critical item in extrusion cooling. Many companies throw water out, even though they may have their own wells. Why not recirculate and reuse with low cost pumps? I started with used pumps from a clothes washer!

First, check the water for quality. Beware of additives that create scale under hot water conditions. From the cooling trough we pushed the water through a small cooling unit and through a water softener. The loss in water was negligible.

See also:

- [Cooling water](#)
- [Cooling water flow](#)
- [Throat cooling](#)
- [Water piping](#)
- [Water valve off](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .