



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Control Systems

Modified on Sunday, 01 February 2015 10:28 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 
(10) » [Warning: Casting Rolls](#) » [Hot Gearbox 1](#) » **Control Systems**

Control Systems
Vol.21 #1, June 1994

When was the last time you looked at your control system? Do you still have the original controllers or data acquisition system?


There have been many advances in controller technology and data acquisition systems since your extrusion system was installed and you have gained insight about your system and its operating characteristics since its installation.

Consider how your system can be revised, modified or replaced so that greater efficiency can be obtained in maintaining your system on target and minimizing variation.

See also:

- [Data collection 1](#)
- [PLC circuits](#)
- [Temperature control](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .