



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Gels 1

Modified on Sunday, 01 February 2015 10:35 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Storage of Extruders](#) » [Hopper Magnets](#) » **[Gels 1](#)**



Gels 1

Vol.21 #2, Oct. 1994


If you experience a severe gel problem after a resin change, check that the vacuum and surge hoppers have been thoroughly cleaned.

Even small amounts of dust from a different resin type can cause a severe gel problem.

See also:

- [Gel identification](#)
- [Gels 2](#)
- [Gels 3](#)
- [Purging gels](#)
- [Removing gels](#)
- [Screen packs 2](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .