



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration

- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Plant Layout

Modified on Sunday, 01 February 2015 10:37 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

(10) » [Gels 1](#) » [Flex Tube Safety](#) » **Plant Layout**



Plant layout


Vol.21 #2, Oct. 1994

When laying out a plant for multiple extrusion lines with multiple resin handling vacuum pumps, it is a good idea to construct a separate room to contain the vacuum pumps and filters. This reduces the noise level around the lines and allows all of the filters to be cleaned at a single location.

See also:

- [Drive train](#)
- [Extruders](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .