



## Navigation



### Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

### Search the Wiki

  [»](#)

### Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

### Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

### Administration

- [Administration](#)
- [File Management](#)

### Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Hose Clamp Safety

Modified on Sunday, 01 February 2015 10:42 PM by [mpieler](#) Categorized as [Extrusion Hints](#)   
(10) » [Lubricate Screw Shank](#) » [Protect Your Hand](#) » **[Hose Clamp Safety](#)**


Hose clamp safety  
Vol.21 #2, Oct. 1994

When cut to length, hose clamps should be filed smooth or covered with duct tape and rotated away from the operator to insure his/her safety.

See also:

- [Zone cooling checkup](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .