



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

 »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



For Safety's Sake! 1

Modified on Sunday, 01 February 2015 10:50 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Adapter Flange Leak](#) » [Start Up 2](#) » **[For Safety's Sake! 1](#)**

For safety's sake! 1
Vol. 21 #3, Dec. 1994

Hopper height must be at least 36" so that an individual's hand cannot get caught in the screw.

See also:

- [Eye protection](#)
- [Flex tube safety](#)
- [For safety's sake 1](#)
- [Hoppers](#)
- [Hose clamp safety](#)
- [Razor knives](#)
- [Safety](#)
- [Safety 2](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .