



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

 »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



For Safety's Sake 2

Modified on Sunday, 01 February 2015 11:27 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Improved Dies](#) » [Feed Rate Limited](#) » **[For Safety's Sake 2](#)**

For safety's sake 2
Vol. 23 #1, May 1996

An extruder feed hopper should be at least 36" high (arm's length) for elimination of the hazard of getting fingers caught in the flights.

See also:

- [Flex tube safety](#)
- [For safety's sake 1](#)
- [Hoppers](#)
- [Hose clamp safety](#)
- [Razor knives](#)
- [Safety](#)
- [Safety 2](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .