



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration

- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



## Colored Mixing Drums

Modified on Sunday, 01 February 2015 11:32 PM by [mpieler](#) Categorized as [Extrusion Hints](#)  
(10) » [Feed Rate Limited](#) » [For Safety's Sake 2](#) » **Colored Mixing Drums** 

Colored mixing drums  
Vol. 23 #2, Oct. 1996


When using various additives for preblending, direct co feeding, or secondary downstream feeds, consider using colored drums to clearly identify the materials.

This should help minimize using or mixing wrong materials.

See also:

- [Color feeder calibration](#)
- [High-low melt blends](#)
- [Storage](#)
- [Time dimension](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .