



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration


- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Zirconia Blades

Modified on Sunday, 01 February 2015 11:34 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

[\(10\)](#) » [Twin Screw Installation](#) » [Power Factor](#) » **Zirconia Blades**

Zirconia blades  
Vol. 23 #2, Oct. 1996


To improve film slitting, use zirconia ceramic blades. These will offer four times the service of carbon steel, heat treated, stainless steel, or nitrated blades.

These blades are useful in slitting LLDPE or ULDPE films.

See also:

- [Roll edge quality](#)
- [Stainless steel components](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .