



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



PET Dryer Instrumentation

Modified on Sunday, 01 February 2015 11:59 PM by [mpieler](#) Categorized as [Extrusion Hints](#) [\(10\)](#) » [Gels 3](#) » [Screw Removal 4](#) » **PET Dryer Instrumentation**

PET dryer instrumentation
Vol. 24 #1, March 1997

When extruding PET, add instruments to your dryer.

Be sure your dew point meter is calibrated. (Also add one in the return air line.)

Put a thermometer through the hopper wall.

Add pressure gauges across filters to detect clogging.

- Russ Gould, RG Associates

See also:

- [Not dry enough](#)
- [PET dryer](#)
- [Polymer drying](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)