



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration


- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Resin supplier

Modified on Monday, 02 February 2015 12:22 AM by [mpieler](#) Categorized as [Extrusion Hints](#)   
(10) » [Avoid Feed Stock Fluidization](#) » [Heater Amps](#) » [Resin supplier](#)

Resin supplier  
Vol. 24 #3, Dec. 1997

Make it a priority to identify your resin supplier's technical service personnel. Then work with them to insure that your requirements are understood and agreed to with your suppliers.


They can be a valuable source of information.

- Paul Bowen, Quantum Chemical Co.

See also:

- [Transitioning](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .