



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Chemical Purge Compound

Modified on Monday, 02 February 2015 12:28 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

[\(10\)](#) » [Pressure Taps](#) » [Rheology](#) » **[Chemical Purge Compound](#)**

Chemical purge compound
Vol. 25 #1, May 1998

Chemical purge compounds can be very effective in cleaning degradation from a screw/barrel, to reduce the need for pulling the screw. Also makes pulling the screw and cleaning it much easier.


A number of them are on the market with good vendor support.

- Ken Powell, Becton Dickinson Research Center

See also:

- [Nylon purge](#)
- [Polymer degradation](#)
- [Purge](#)
- [Purge 2](#)
- [Purge compound](#)
- [Purging gels](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .