



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Restrictive Adapter

Modified on Monday, 02 February 2015 12:29 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 
(10) » [Chemical Purge Compound](#) » [Heater Burnout](#) » **[Restrictive Adapter](#)**

Restrictive Adapter
Vol. 25 #1, May 1998


Adequate pressure generation is required in extrusion to offset back flow in single screw extruders. To maximize the melt stability on materials exhibiting pressures of 1000 psi or less, restrictive adapters is an alternative solution to increasing screen packs.

- Dan Cykana, Bemis Mfg. Co.

See also:

- [Adapter flange leak](#)
- [Adapter flow](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .