



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

 »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



Chromium Plating Test Solution

Modified on Monday, 02 February 2015 12:36 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Safety 2](#) » [Sweep Up](#) » **Chromium Plating Test Solution**

Chromium plating test solution
Vol. 25 #2, Sept. 1998

Copper Sulfate is needed to validate whether chrome plating is still present on a plated stainless steel calibrator.

Normal wear can polish the parent steel, if running for an extended time period, giving the illusion of full chrome coverage.

- Daniel Cykana, Bemis Manufacturing

See also:

- [Calibrate tachs](#)
- [Color feeder calibration](#)
- [Stainless steel components](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)