



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Twin Screw Extrusion

Modified on Monday, 02 February 2015 12:40 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 
(10) » [Mini Microscope](#) » [Turn the Screw by Hand](#) » [Twin Screw Extrusion](#)

Twin screw extrusion
Vol. 25 #2, Sept. 1998


When transferring screw designs between twin screw extruders having different L/D ratios, address the design analysis on three levels: overall length, relative length of solids and melt conveying zones, and functional zones such as preheating, melting, mixing, and pumping. Compare lengths in terms of L/D ratios.

- Kun Sup Hyun, The Dow Chemical Co.

See also:

- [Drive ratio](#)
- [Twin scale uP](#)
- [Twin screw changes](#)
- [Twin screw extruder](#)
- [Twin screw extrusion 2](#)
- [Twin screw extrusion \(3/99\)](#)
- [Twin screw help](#)
- [Twin screw installation](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .