



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

 »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



Product Variations

Modified on Monday, 02 February 2015 12:42 PM by [mpieler](#) Categorized as [Extrusion Hints](#) [\(10\)](#) » [Twin Screw Extrusion](#) » [Monitor Heaters](#) » **Product Variations**

Product Variations
Vol. 25 #2, Sept. 1998

Product variations of a cyclic nature are almost never related to the die.

When cyclic variations do occur, variations in the polymer resin, temperature, throughput, and line speed should be investigated and corrected, as necessary.

- Wayne Gifford, Extrusion Dies, Inc.

See also:

- [Temperature control](#)
- [Throughput checks](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .