



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration


- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



## Twin Screw Extrusion (3/99)

Modified on Monday, 02 February 2015 12:51 PM by [mpieler](#) Categorized as [Extrusion Hints](#)   
(10) » [Pressure Transducers 2](#) » [Travel Tip](#) » [Twin Screw Extrusion \(3/99\)](#)

Twin screw extrusion (3/99)  
Vol. 26 #1, March 1999


Different resins respond differently to adjustments in the ratio of solids convey to melt conveying, but melt temperatures generally decrease with increased solids conveying distance. Other responses to consider are melt quality and overall energy requirements.

- Kun Sup Hyun, The Dow Chemical Co.

See also:

- [Twin screw extruder](#)
- [Twin screw extrusion](#)
- [Twin screw extrusion 2](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .