



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Oatmeal

Modified on Monday, 02 February 2015 01:02 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

(10) » [Unmixed Polymer Gels](#) » [Cool Dryer Return Air](#) » **Oatmeal**

Oatmeal
Vol. 26 #2, September 1999


Oatmeal is a good, inexpensive, purge material for extrusion applications run at low temperatures or with sensitive materials.

- D. Bigio, University of Maryland

See also:

- [Purge](#)
- [Purge 2](#)
- [Purge material](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .