



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Consistent Air

Modified on Monday, 02 February 2015 01:02 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 


[\(10\)](#) » [Oatmeal](#) » [Flow Instability](#) » **Consistent Air**

Consistent Air
Vol. 26 #2, September 1999

Consistency of plant air pressure can play a key role in sheet quality. Changes in air pressure can affect nip roll pressure, which affects sheet thickness consistency. Watch out for intermittent uses of plant air such as cutters, etc.

- Dan Smith, Maag

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .