



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

 »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Output Rate Check

Modified on Monday, 02 February 2015 01:05 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

(10) » [Spread Sheets](#) » [Screw Cooling \(Dec99\)](#) » [Output Rate Check](#)



Output Rate Check

Vol. 26 #3, December 1999

There are many techniques for measuring extruder output rate. The type used depends on the size, type, and accuracy of a conveniently available scale. For extrusion rate check using gram weight measurement:

- measure the rate over a 79 second time period
- measure the weight in grams

Multiply by 0.1 to get rate in pounds per hour (PPH).

- John Wagner, JWV Enterprises

See also:

- [Checking extrusion output rates without the use of a calculator](#)
- [Extruder output](#)
- [Output calculations](#)
- [Output rates](#)
- [Output variation 1](#)
- [Output variation 2](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)