



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Lap Stone

Modified on Monday, 02 February 2015 01:25 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 
(10) » [Aligning a Blown Film Tower](#) » [Polymer Degradation](#) » **Lap Stone**

Lap Stone

Vol. 27 #3, December 2000


This removes burrs from the faces of twin screw extruder elements. It is also useful for removing nicks from breaker plates and die parts. Use them to sharpen knives.

- Paul Andersen, Krupp Werner & Pfleiderer

See also:

- [Leaks](#)
- [Twin screw extruder](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .