



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Crystalline Structure

Modified on Thursday, 26 February 2015 03:57 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Purging \(2\)](#) » [Screen Pack](#) » [Crystalline Structure](#)




Crystalline Structure
Vol. 33 #1, Summer 2006

Often, we need to understand the rate at which structure is developed in semi crystalline polymers during film produc- tion. Several years ago, we published a relatively simple method using an inexpensive laser and relatively simple video frame grabbing system.

– Greg Campbell, Clarkson University

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .