



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Seed Counter

Modified on Sunday, 01 February 2015 05:31 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

[\(10\)](#) » [Purging Gels](#) » [Sheet Pinning](#) » **[Seed Counter](#)**


Seed Counter
Vol. 19, #2, June 1992

For laboratory twin screw extruders, a seed counter can work effectively as a controlled feed rate device. Professors at land grant universities may want to check with their Agronomy departments for use of a seed feeder. Often, these units are only used by the Ag department for a few weeks in the spring.

See also:

- [Lab extruders](#)
- [Twin screw](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .