



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration

- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Flex Tube Safety

Modified on Sunday, 01 February 2015 10:36 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

(10) » [Hopper Magnets](#) » [Gels 1](#) » **[Flex Tube Safety](#)**


Flex tube safety  
Vol.21 #2, Oct. 1994

When purchasing flexible plastic tubing for use in resin or fluff handling systems, make sure the tubing has a built in wire to provide a drain for the static charge that can build up on non conductive tubing.

See also:

- [Reduce static in polymer processing operation](#)
- [Static electricity build up](#)
- [Static eliminator](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .