



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



Pressure Transducers 2

Modified on Monday, 02 February 2015 12:57 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Dryer Inlet Air](#) » [Rules of Thumb](#) » [Pressure Transducers 2](#)

Pressure transducers 2
Vol. 25 #3, Dec. 1998

Pressure transducers are useful for protecting extruders from over pressure when properly selected for pressure range. Regular inspection and maintenance combined with correct alarm point settings for safe pressure limit will protect operators and prevent equipment damage. In process monitoring of these instruments will likely help troubleshoot processing problems.

- Bill Corcoran, Dupont Co.

See also:

- [Pressure transducer handling](#)
- [Pressure transducers](#)
- [Rules of thumb](#)

[Return to Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#)