



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki


»

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration

- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Pre-Drying Moisture Sensitive Polymer

Modified on Monday, 02 February 2015 01:08 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

(10) » [Deviation Alarms](#) » [Cross Contamination \(Extrusion Hint\)](#) » [Pre-Drying Moisture Sensitive Polymer](#)



Pre-Drying Moisture Sensitive Polymer  
Vol. 27 #1, March 2000


When pre-drying a moisture sensitive polymer, it is important to remember that any component that is volatile at less than the specified drying temperature may also be removed. This would include additives such as plasticizers, lubricants, and fire retardants. The removal of these additives may affect the properties of the product being extruded and they may also contaminate the dryer's desiccant beds.

- Pete Stoughton, Conair

See also:

- [Condensation](#)
- [Dehumidifying dryers](#)
- [Dryer inlet air](#)
- [Drying temperature](#)
- [Installing a dehumidifying drying system](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .